


CPC 11-4
206429-1



TO USE THIS TEST CONNECTOR, REMOVE JB2 AND AND JB6 OF THE STAGE INTERCONNECT BOX. CONNECT A TEST MOTOR TO THE RED AND BLACK WIRES OF THIS TEST CONNECTOR AND CONNECT THE MOTOR ENCODER TO JB6. COMMAND THE MOTOR TO JOG. IF THE MOTOR 'RUNS AWAY' SWAP THE MOTOR LEADS. WITH THE MOTOR RUNNING VERIFY THAT THE MOTOR STOPS WHEN THE LIMIT SWITCH IS ACTUATED.

UNIVERSITY OF CALIFORNIA
LICK OBSERVATORY

GALIL MOTOR/SECONDARY LIMIT
TEST CONNECTOR

REVISION

DES'N BY: B. Alcott

ORIGIN DATE: 12-11-01

DWG. NO.

NUM. 1 OF 1

Last SN:

MODIFY DATE:

PATH: MULTIPURPOSE\EL-1296\MOT_SEC_LIM_TEST

REV. A

EL-1296